Requisite Validation Template

Program Code: T942

Program Title: Power Engineering Technician

Program Version Code: 25F

Semester 1		
Course Code	Pre-Requisite Code(s)	Co-Requisite Code(s)
PSE119	None	None
MTH143	None	None
PSE142	None	None
PSE151	None	None
PSE124	None	None
PSE117	None	None
PSE129	None	None
PSE118	None	None

Semester 2		
Course Code	Pre-Requisite Code(s)	Co-Requisite Code(s)
PSE445G	None	None
MTH243	MTH143	None
PSE217	None	None
PSE219	PSE119, PSE151	PSE203, PSE221
PSE203	PSE124	None
PSE222	None	None
PSE221	None	None

Semester 3		
Course Code	Pre-Requisite Code(s)	Co-Requisite Code(s)
PSE315	To be ELIGUBLE for this work placement the student MUST successfully complete all first year Power Engineering Technology courses with an overall GPA equal to or greater than 2.0. Signed Unpaid Work Placement Policy form, specific trade and safety training and/or other requirements of the employer, which may also include police clearance, proof of immunization, etc. must be completed. The student must be prepared to go anywhere in Ontario and assume that the position is unpaid. May include weekends and shift work. Individual transportation is required	None
	Or:	

PSE 317	To be ELIGIBLE for this co-op the	None
	student MUST successfully complete all	
	first year Power Engineering	
	Technology course with an overall GPA	
	equal to or greater than 2.0. Specific	
	trade and safety training and/or other	
	requirements of the employer, which	
	may include police clearance,	
	immunization, etc. must be completed.	
	The student must be prepared to go	
	anywhere in Ontario. May include	
	weekends and shift work. Individual	
	transportation is required.	

Semester 4		
Course Code	Pre-Requisite Code(s)	Co-Requisite Code(s)
PSE414	PSE219	None
PSE407	PSE118, MTH243	None
PSE411	MTH243	None
PSE418	PSE117, PSE124	None
PSE416	PSE129	None
PSE419	PSE119, PSE124	None
PSE478	None	None

Semester 5		
Course Code	Pre-Requisite Code(s)	Co-Requisite Code(s)
PSE521	PSE151	None
PSE517	PSE203	None
PSE508	PSE221	None
PSE519	PSE217	None
PSE518	PSE414	None

Semester 6		
Course Code	Pre-Requisite Code(s)	Co-Requisite Code(s)
PSE611	To be ELIGIBLE for this co-op the student MUST successfully complete all Power Engineering courses in previous semesters with an overall GPA equal to or greater than 2.0. Students must have 4th Class power engineering certificate or PSE315 or PSE317 Specific trade and safety training and/or other requirements of the employer, which may also include police clearance, proof of immunization, etc. must be completed. The student must be prepared to go anywhere in Ontario.	None

	May include weekends and shift work. Individual transportation is required.	
	Or:	
PSE 617	To be ELIGIBLE for this co-op the student MUST successfully complete all Power Engineering courses in previous semesters with an overall GPA equal to or greater than 2.0. Students must have 4th Class power engineering certificate or PSE315 or PSE317 Specific trade and safety training and/or other requirements of the employer, which may also include police clearance, proof of immunization, etc. must be completed. The student must be prepared to go anywhere in Ontario. May include weekends and shift work. Individual transportation is required.	None